


# Critical Drainage Area (CDA)

## Torrige District Council - East the Water

May 2015



### Catchment Drainage/Flooding Issues

The surface water drainage systems of East the Water has numerous known flooding issues, with the main problems along Torrington Street and the roads leading to this area. The Nutterberry Stream also has problems near the electrical depot and Torrington Street. We are also aware of some Sewer flooding that may be exacerbated by heavy rainfall. The catchment also has development pressure from new housing and commercial developments.

The surface water systems and watercourse are unlikely to attract funding for significant improvements, and given that current rainfall runoff rates already cause problems and climate change will increase the frequency of flooding further, alternative measures need to be applied.

### Minimum Drainage Standards Required

All new development will have to play their part in reducing current rainfall runoff rates. This requirement also applies to brown field sites that will have to match the same standards. The SuDS hierarchy should be followed, by using infiltration as far as is practicable. Further guidance on such systems can be found in the CIRIA SUDS manual and in LLFA guidance.

All off-site surface water discharges from development should mimic "Greenfield" performance up to a maximum 1 in 10 year discharge rate. On-site all surface water should be safely managed up to the "1 in 100+climate change" conditions. This will require additional water storage areas to be created thereby contributing to a reduction in flooding downstream.